



## ***Chrysler PT Cruiser All models with 2.4-litre engine Model year to 05/2000***

### **Engine control lamp illuminates, fault code in the fault memory.**

If there are complaints with these vehicles that the engine control lamp illuminates and that fault code P0441 (Flow monitoring suction system carbon filter) is stored in the fault memory, one possible cause may be a software fault in the engine control unit. The driving behaviour of the vehicle is not affected by this fault. In order to eliminate the fault, the software of the engine control unit must be updated.

#### Note:

The software of the engine control unit can be updated only by an authorized dealer.

**Bulletin**

