Bulletin



© Hella KGaA Hueck & Co., Lippstadt 3 May 2007 1-1

Chrysler Voyager, model year 2001–2002

Inaccurate fuel gauge.

If there are complaints with these vehicles that the fuel gauge shows incorrect values or is inaccurate, one possible cause the body control module (BCM). A software fault can result in the above-mentioned faults. In order to eliminate the fault, new, modified software must be installed on the control module.



