



Hyundai Santa Fé Model year 2001–2005 With air conditioning system

Noises due to dripping condensed water

In the case of some vehicles from the above-mentioned production period, noises can arise due to dripping condensed water. The condensed-water drain is positioned in such a way that the water can drip onto the exhaust system. This leads to noticeable “hissing” noises, which could be misinterpreted and lead to various other defects being suspected. As a remedy, the vehicle manufacturer offers a modified condensed-water drain pipe, which should be fitted in the event of a complaint.

2

4

Bulletin