



Jeep

Cherokee

Model year: 2006/2007

With automatic transmission

Blower motor overheats / fails

With the above-mentioned vehicles, overheating can lead to failure of the interior blower fan. The fan is in the footwell on the passenger side.

The problem affects vehicles of the model years 2006/2007 built before 15th August 2006 that have automatic transmission.

The vehicle manufacturer has already recognized the problem and informed the vehicle owners affected. It must be assumed, however, that for a variety of reasons not all vehicles have been checked or fans been replaced.

Please bear this information in mind when complaints are made about noise development on the vehicle interior or failure of the fan.

Bulletin