## **Bulletin**



© Hella KGaA Hueck & Co., Lippstadt 7. März 2005 1-1

## Land Rover Defender model year: 06/1998 - 2004 Discovery II model year: 01/1999 - 2004 With diesel engine: Td5

## Engine warning light illuminates / no engine throttle response

If the engine warning light illuminates on the above vehicles when driving, and if there is no throttle response, this may be due to a faulty plug-connection for the accelerator pedal sensor on the accelerator pedal (see picture). Firstly, a check should be made as to whether the sensor connector is truly locked into place, and cannot be removed. If the problem is still present even after checking the plug-connection, the fuses should be checked, and the accelerator pedal sensor should be checked with the aid of a circuit diagram.



## Bulletin

