



Mercedes Benz C-Class (W203) All models with engine 111 and 112

Ticking noises on the interior.

If there are complaints with these vehicles that ticking noises can be heard on the interior, one possible cause is the timed valve of the evaporative emission control system. The noises are transferred to the bodywork via the valve brackets the lines are clipped into. To eliminate the fault the attachment clips for the lines have to be replaced.

The replacement clips required can be purchased from the local authorised dealer.

The modified clips have been being installed in the factory since model year July 2001.



Attachment clips

Timed valve