



Mercedes Benz E-Class (W210)

All models

With engine: 290 / 300 D Turbo

200 / 220 CDI

Pre-heating warning light does not illuminate and/or illuminates occasionally during trips.

If there are complaints with these vehicles that the pre-heating warning light does not illuminate and/or occasionally illuminates during trips, one possible cause is a faulty final heating level. The fault code P1482 can be stored in the engine control unit fault memory. To eliminate the fault the final heating level has to be renewed.

Then delete the fault memory and check the pre-heating system for perfect function.

Bulletin

