



Mercedes

Type: C-Class (203)

VIN: XXX XA to 053800

XXX XF to 029782

XXX XR to 003328

Incorrect specifications on the safety data sheet

With the above-mentioned vehicles, the data sheet in the fuse box on the driver side can contain incorrect specifications. The white data sheet with the fuse assignment plan prescribes 20 A fuses for fuses No. 3 and No. 16. 7.5 A is correct, however. The correct fuses (7.5 A) are included in the fuse box itself. This means these do not have to be replaced.

The information must be heeded particularly during troubleshooting and within the context of repair work. The old assignment plan should be changed accordingly and/or the data sheet replaced. The changed data sheet, which can be obtained from the authorised dealer, is green (see illustration).

