



Mercedes-Benz C-Class 220 CDI (W 203) Model year from 07.2002 to 03.2003 With engine 611.962

Poor engine running

If there are complaints from customers about the above-mentioned fault, the fuel filter could be the cause. In addition, the fault code P1187 (fuel distributor pressure sensor - faulty function) could be stored. Under certain circumstances, air can be enclosed behind the fuel filter (on the low-pressure side of the fuel system), resulting in this fault. In this case, a modified fuel filter has to be installed. Then delete the fault memory.

Bulletin

