



Mercedes-Benz C-Class W 203

Malfunction of the electrical pop-up/sliding roof.

If there are complaints with these vehicles that the electrical pop-up/sliding roof does not work properly, one possible cause is the roof control module. This roof control module loses stored data due to a software fault. When the pop-up/sliding roof is activated, it only moves jerkily. The roof control module must be replaced for the fault to be eliminated. The sunroof motor does not have to be replaced and its replacement will not eliminate the problem.

Note:

When ordering a new roof control module make sure you order the right colour.

Bulletin

