



MINI R50 / R52 / R53 (Cooper S) With CVT gearbox

Insufficient power of the air conditioning system / coolant loss

Problem:

A defective coolant line can cause the failure of the air conditioning system.

Possible cause:

Pay attention to the line between the condenser and the evaporator. The line may have scoured on the gearbox and be damaged as a result.

Solution of the problem:

Renew the defective line and lay such that contact with the gearbox is avoided under all circumstances.

The information is limited to vehicles equipped with a stepless (CVT) gearbox.

Bulletin