



## **MINI**

### **R50 | R52 | R53 (Cooper S)**

### **With manual air conditioning system**

#### **Temperature regulation not possible**

##### **Problem:**

Adjusting the temperature via the control element is no longer possible.

##### **Possible cause:**

The mixed air flap lever comes loose from the flap shaft.

##### **Solution of the problem:**

Re-install the flap lever in the area of the heating/evaporator box and secure with adhesive.

The information is limited to vehicles equipped with a manual air conditioning system.