



Nissan Terrano II, all vehicles with VIN VSKxxxR20U 0277801-0325004

Bad idling

If this fault is complained about, then a possible cause can be a defective accelerator pedal sensor. Additional complaints may concern bad throttle response during acceleration and that the engine control lamp goes on. In that case, the accelerator pedal sensor needs to be replaced.

Bulletin

