



## **Opel Astra G**

### **Model year: 1998–2004**

### **Engine: Z17DTL / Y17DTL**

#### **Charge control lamp flickers or illuminates constantly.**

If there are complaints with these vehicles that the charge control lamp flickers or illuminates constantly, one possible cause is a damaged cable on the D+ connection on the alternator. The blue/white cable on the D+ connection chafes on the housing of the alternator, which leads to the insulation being damaged. The damaged insulation causes an earth connection on the alternator housing and gives rise to the above-mentioned fault. In order to eliminate the fault, the cable must be repaired and laid in such a way that renewed damage is avoided.