



Opel Astra H, Zafira B Model year 2005 Engine: Z20LEL, Z20LER

Clacking noises when idling / Compressor clutch switches permanently

In the case of the above-mentioned vehicles, clacking noises may occur, mainly when idling. These are caused by the permanent switching-off and switching-on of the magnetic clutch of the compressor. Here, the cause does not necessarily lie in the system components or the quantity of refrigerant. Often, the problem can be solved by installing new software for the engine control unit. Modified software was used at the factory from model year 2006.

Bulletin