



## **Opel Monterey With a 3.0 DTI (4JX1) engine**

### **The engine has start-up problems when it has been at a standstill for some time.**

If there are complaints with these vehicles that the engine has problems starting up (up to 3 minutes start-up time) after it is been at a standstill for some time, one possible cause is the formation of air bubbles in the fuel filter element. To eliminate the fault a modified fuel filter element has to be installed. To do this proceed as follows:

- Remove fuel filter element.
- Take the switch and drain screw off the old filter element and fix them to the new filter element.
- Clean the sealing face and install the new filter element.
- Ventilate the fuel system.
- Start the engine and carry out a leak test.