

12th June 2006

Opel Omega B Model year: 1994 + 1995 With manual air conditioner

Windscreen fogs up

With the above-mentioned vehicles the windscreen can fog up when the air conditioner is switched on. This occurs particularly often when the engine has just been started up. The problem is usually caused by residual humidity. This has collected on the surface of the evaporator and is blown with the airflow onto the windscreen, where it then condenses. To remedy the problem, the airflow should be directed towards the footwell before the air conditioner is switched on, and the fan speed set to high.

The evaporator dries within 1-2 minutes and the airflow can then be rerouted to the windscreen.

The above-mentioned problem can also occur with other vehicle models and can also be eliminated with the same procedure.

Ulletir





1-1

