



Opel
Omega B
Model year: 1994 - 09.1996
Vectra B
Model year: 1995 - 09.1996
Engine: all
With automatic air conditioning

Operating unit for air-conditioning system

With the above-mentioned vehicles, the keys on the air-conditioning operating unit can become difficult to press, or can no longer be pressed at all. In some cases the keys stick. This means that the functions can no longer be carried out. The problem is caused by a difference in coating thickness of the key guides.

The installation of a new operating unit can remedy the problem. Vehicles manufactured from September 2006 onwards already have modified operating units.

Bulletin