



Opel **Vectra-B model year 1999 – 2001** **Omega-B model year 1999 – 2001**

Central locking anti-theft function does not activate.

If there are complaints with these vehicles that the central locking anti-theft function does not activate, one possible cause is a defective or corroded door contact switch on the driver's door.

To rectify the fault, the door contact switch for the driver's door must be checked for corrosion and damage. If no faults can be found, the door contact switch should be checked for continuity and, if necessary, replaced.

If the door contact switch is OK, the control unit for the central locking / anti-theft alarm may have to be replaced. In this case, the new control unit and the keys must be reprogrammed.