



Opel Zafira (B) Model year 2005 + 2006

Failure of the air-conditioning system /Battery discharged

In the case of the above-mentioned vehicles, a defective harness for the air-conditioning system can cause the air-conditioning system to fail. Consequently, it is possible for the battery to become discharged.

The vehicle manufacturer has written to all vehicle owners regarding its service campaign in relation to this problem. In the course of checking, modified harnesses were fitted if necessary. However, it may well be that not all vehicle owners have made use of the free-of-charge check/conversion, resulting in vehicles on which the above-mentioned problem can occur still being in circulation.

Bulletin