## **Bulletin**



© Hella KGaA Hueck & Co., Lippstadt 29.10.2007 1-1

## Renault Kangoo 1.6L From model year 12.2002 All vehicles with engine code K4.

## **Poor engine running**

If there are complaints about the above-mentioned fault, a faulty ignition coil could be the cause. This is noticed on the basis of rough idling and during acceleration. Ignition coils marked with Renault part numbers up to 330-03 must be replaced. This number can be found on the upper part of the ignition coil (see illustration).



Diagnosis of the ignition coils should always be carried out before replacement, however. The ignition coil with the Hella no. 5 DA 749 475-161 can be purchased on the aftermarket.



