



Rover 45

All models

Chassis nos. RT471064 - RT506310

Failure of fuse no. 5 in the fuse box in the engine compartment.

If there are complaints with these vehicles that fuse no. 5 in the fuse box in the engine compartment is burnt out, one possible cause is that the fuse inserted is not strong enough. To eliminate the fault and prevent the fuse burning out again, the old 10 A fuse must be replaced by a more powerful 20 A fuse.

Note the fuse replacement in the operating manual and in the assignment plan of the fuse box. Appropriate labels and data sheets for the operating manual can be obtained from Rover dealers.

Bulletin

