



Saab 9-3 **Up to chassis no.: X2030478 or** **X7024091**

Hazard warning system is activated independently.

If there are complaints with these vehicles that the hazard warning system is activated independently, one possible cause of the fault is the DICE – control unit (DICE = **D**ashboard **I**ntegrated **C**entral **E**lectronics).

In this case, one of the capacitors in the control unit fails, resulting in the hazard warning system being activated independently. In order to eliminate the fault, the control unit must be replaced.

The control unit is installed on the left-hand side of the dashboard below the instrument panel (see drawing).

