## **Bulletin**



© Behr Hella Service GmbH, Schwäbisch Hall	01. Oktober 2005	1-1
--	------------------	-----

## VW-Passat (Type: 3B2+3B5)

## Water ingress due to a blocked drain in the water-box

In the gap between bonnet and windshield, leaves can get into the water box (see pic.). They can block the drain below the battery. This leads to "overflowing" of the water-box. Consequently water can get into the interior of the vehicle.

To remedy, proceed as follows:

- 1. Remove the battery
- 2. Clean the water-box drain
- 3. Install the battery
- 4. Enter the radio code
- 5. Adjust the clock



## Bulletin

