



Fiat Marea Weekend Model year from 1999 to 2003

Engine warning light comes on

If there are complaints about the above-mentioned problem, a faulty speed sensor could be the cause. This transmits a faulty signal to the engine control unit which causes the above problem to occur. In addition, the speedometer could fail sporadically. In this case, read out the fault memory. If the fault is currently stored, the speed sensor has to be replaced. This is installed on the gear. Delete the fault store after replacement.

Bulletin