



Fiat

Punto (188)

Model year: from 09.1999

Engine: 1.2 i (44 KW)

Engine warning light flashes / Fault code P1300

With the above-mentioned vehicles the engine warning light can start to flash during driving, although no driving problems occur. If, at the same time, fault code P1300 (self-teaching trigger wheel) is stored in the engine control unit, repeated teaching of the trigger wheel can remedy the problem. First, however, all the ignition-related components must be checked to make sure they are OK.

Teaching process trigger wheel:

- Get the engine up to operating temperature (> 80°C) and stop it.
- Start the engine and let it run in idle, making sure all large current consumers are switched off (light, heating, air conditioning).
- Accelerate 3 times in succession to more than 5000 rpm, then releasing the pedal completely every time. Wait between revving up for the engine to reach idling speed again.
- Stop the engine and wait for at least one minute with the ignition switched off.
- Start the engine and observe whether the engine warning light goes off.
- Carry out a test drive.