



Ford Focus Model year 08/1998 to 09/2000 All models with central locking and radio remote control

Low range or poor function of the remote control.

If there are complaints with these vehicles that the radio remote control has a low range or does not work at all on occasions, one possible cause is the central safety module. The range of this is too low and it does not communicate with the radio remote control. A modified module and additional cable aerial have to be installed to eliminate the fault. To do this proceed as follows:

- Remove the central safety module on the right behind the glove box.
- Loosen the plug connections from the module.
- Insert the connection of the additional cable aerial into the free Pin 9 of the green plug.
- Connect the new module and reinstall it.
- Lay the cable aerial along the cable strand to the driver side. On the driver side, loosen the scuff plate and lay the cable aerial beneath the scuff plate next to the cable strand along the sill.
- Fix the scuff plate back into place.

Note:

A modified central safety module and cable aerial have been being installed in the factory since October 2000.