



Ford Mondeo

Model year: up to 11/1995

Engine: 1.8-litre turbo diesel

With air conditioner

Engine cannot be switched off with the air conditioner switched on

If the warmed-up engine of the above-mentioned vehicles cannot be switched off, the vehicle has possibly not been retrofitted with an additional cable. This cable, which is fitted with a diode and available through Ford dealers, is inserted between the 16-pin plug and the central electric box (see drawing). To do this proceed as follows:

- Remove the lower footwell cover (LHD) or pull out the glove box (RHD)
- Pull the 16-pin plug off the central electric box
- Insert the additional cable and reconnect the plug
- Refit the footwell cover or the glove box
- Carry out a functional test

