



Ford

Mondeo I (GBP / BNP)

Model year: until May 1994

With Zetec engine

Coolant loss

If coolant loss is found in the case of the above-mentioned vehicles, particular attention should be paid to the coolant pipe/coolant hose from the heating return line. If it is found that the pipe or the hose is damaged, or that coolant is escaping, the defective parts should be replaced with modified ones. The modified coolant pipe, which was also fitted as standard by the vehicle manufacturer from May 1994, has an additional holder which is fastened to the centre bearing of the drive shaft.

Bulletin