



Ford Transit Model year: up to August 1996 Engine: 2.0 ltr DOHC With MT75 manual gearbox Left-hand drive (LHD)

Poor cooling performance / Loss of refrigerant

With the above-mentioned vehicles, a damaged refrigerant pipe can lead to loss of refrigerant from the air-conditioning system.

If the air conditioning is working insufficiently or not at all, the pipe from the dryer/accumulator to the condenser should be checked for damage. The pipe can have been frayed by the clutch pedal. The lower engine cover must be removed for the pipe to be inspected. If the pipe is damaged, it must be replaced. Care must be taken that an additional attachment is used to fix it in place (see drawing) and that it does not come into contact with other components or the clutch cable.

