



## **Kia Sportage Model year: 2002**

### **Radiator fan blade / engine overheats**

With the above-mentioned vehicles, tough everyday use or offroad use can lead to the radiator fan blade breaking. As a result, the engine can overheat. The radiator can also be damaged by the faulty fan blade.

This problem affects vehicles built in 2002 and with the VIN: KNEJA 543425108335 – 563535180392.

The vehicle manufacturer has already recognized the problem and informed the vehicle owners affected. It must be assumed, however, that for a variety of reasons not all vehicles have been checked and/or repaired.

Please bear this information in mind when complaints are made about engine temperature, noise and loss of coolant. You can find new radiator fans in the BHS spare parts range.

