



## **LANCIA**

### **Phedra**

### **Year of manufacture: 2002 - 2005**

#### **Condensed water drain / Airbag control lamp**

**Problem:**

Water may accumulate in the front passenger footwell.

**Possible cause:**

Inadequate drainage of the condensed water from the air conditioning system. In some cases the water also accesses the airbag control system, which may cause the control lamp to light up. In extreme cases the trigger function of the airbag(s) is activated.

**Solution of the problem:**

Check/clean the condensed water drain and inspect the airbag control system for water penetration. Furthermore, additional information with regard to remedial measures must be obtained from the vehicle manufacturer.