Bulletin



© Behr Hella Service GmbH, Schwäbisch Hall 5 February 2007 1-1

Lancia Ypsilon Model year: 11.2005–05.2006 With air-conditioning system

Evaporator ices up

lcing-up of the evaporator may occur in the case of the above-mentioned vehicles, which were made between November 2005 and May 2006. In extreme cases, this leads to occasional failure of the air-conditioning system. Here, the problem can be resolved by a software update. In relation to this, it is advisable to contact an authorized dealer. The vehicle manufacturer had a service campaign with regard to the problem. However, it may well be that not all vehicle owners made use of this, resulting in vehicles with the old software status still being in circulation.



