



Mercedes Benz C-Class (W202) CLK (W208) E-Class (W210) All models with anti-theft alarm

Occasional triggering of the alarm for no apparent reason.

If there are complaints with these vehicles that the anti-theft alarm occasionally sounds for no apparent reason, one possible cause is the infrared interior-protection sensors. The fault often occurs after locking the vehicle or after long periods of standstill. In order to eliminate the fault, the anti-theft alarm should be checked for other faults. If no other faults are present, the infrared interior sensors must be replaced.