



## **Mercedes C-Class (203)**

### **Windscreen becomes fogged**

In some of the above-mentioned vehicles it may be that under certain operating conditions, the windscreen becomes fogged. Here, it is not the entire screen that becomes fogged, but rather just a triangular area in the lower-middle section of the screen.

In order to resolve the problem, the air distribution grille for the central air vent (above the dashboard) should be replaced with a modified air grille. This can be obtained from the vehicle manufacturer. Vehicles affected are those with vehicle identification numbers: xxx xA to 237174 and xxx xF to 183960. The air distribution grille can be removed easily by unclipping it (see photo) and removing it upwards.



**Bulletin**