



Mercedes C-Class (W202) Vehicle identification no.: up to A344660, up to F331440

Heat exchanger / Additional hose

The heat exchanger (heating radiator) may leak in the case of the above-mentioned vehicles. If, in relation to this, the existing heat exchanger is replaced with a heat exchanger from the "independent aftermarket" (e.g. Behr Hella Service, part no. 8FH 351 311-761), an additional hose (A0018309315), which can be obtained via the vehicle manufacturer/authorized dealer, must often be used as well.

Bulletin