



## **Mercedes Benz E-Class (W210) C-Class (W202) All models with tilt/slide sunroof**

### **Tilt/slide sunroof malfunction.**

If there are complaints with these vehicles that the tilt/slide sunroof does not work properly or stops, one possible cause is a defect in the overhead control unit. Failure of a processor causes the overhead control unit to lose its programming. In order to eliminate the fault, a new overhead control unit must be installed. After installation, the new overhead control unit must be reprogrammed. To do this, move the sunroof into the tilt position and hold the switch for longer than 1 second.

#### **Note:**

A modified control unit was installed in vehicles manufactured after January 1999.

**Bulletin**

