



Mercedes Benz W 124 with anti-theft alarm

Anti-theft alarm cannot be activated/deactivated using the key.

If there are complaints with these vehicles that the anti-theft alarm cannot be activated or deactivated using the key for the vehicle, one possible cause is a defective contact on the door lock.

In this case, the reed contact (lock button) on the left-hand door lock is defective or broken. To rectify the fault, the contact must be replaced.

As the old version of the reed contact is no longer available, the entire lock cylinder must be replaced with a new one which has an integrated contact.

Bulletin