



Mercedes Benz W210 and W220 All models

Fault code stored in the fault memory of the airbag control unit.

If there are complaints with these vehicles that fault codes B1310 and B1311 (communication fault) are stored in the airbag control unit and cannot be deleted, one possible cause is the manufacturer of the control unit and the manufacturer of the side airbag sensors being different. This fault often occurs after replacement of the control unit or the sensors. To eliminate or avoid the fault, it must be ensured when replacing the control unit or the sensors that both components are from the same manufacturer.