



## **MINI**

**(R50/52/53)**

**Year of manufacture: up to March 2005**

### **Condensation water runoff clogs water entry into the cable tree**

**Problem:**

Entry of condensation water into the cable tree causes continuous lighting of brake lights.

**Possible cause:**

Constricted or clogged condensation water runoff

**Remedy:**

Check and if necessary clean the cross-sections of the condensation water runoff hoses. Also make sure that the runoff cross sections are not constricted by the cable tree. It may be necessary to re-install the cable tree. Visually check the parts and the cable tree for water; if necessary, repair them.

**Bulletin**