



## **Opel**

***Astra F, with air conditioning system***

***Model year: 1992-1997***

***Omega B, with air conditioning system***

***Model year: 1994-1997***

### **Interior blower without function**

If the interior blower motor in the above-mentioned vehicles should fail or reveal malfunction, this can be connected with operation of the air conditioning system. Operating the air conditioning system can lead to the collector of the blower motor icing up. This leads to malfunctions and/or to complete motor failure. In cases of complaint the blower motor should be replaced. Blower motors can also be found in the *Behr Hella Service* range (photo shows the motor for the Astra F).



**Bulletin**