Bulletin



© Behr Hella Service GmbH, Schwäbisch Hall 5 February 2007 1-1

Opel Astra H Model year: 2004 to 2005 With engine: Z14XEP, Z16XEP, Z18XE Vehicles with automatic air conditioning

Compressor noises

Externally-controlled compressors are used in the case of the above-mentioned vehicles. Here, if there are complaints with regard to noises that occur at an engine speed of 1,500 2,000 revolutions per minute, it may be possible to eliminate these noises through a software update.

Before replacing the compressor, it is essential that the software status of the air-conditioning-system control is checked and, possibly, updated. In relation to this, it is helpful to contact an authorized dealer.



