



## **OPEL**

### **Astra H + Zafira B**

### **Model year: 2007 + 2008**

### **Engine: 1.8 + 2.2 l petrol engine**

### **With automatic transmission**

#### **Coolant radiator leaking / Coolant in the automatic transmission**

With the above-mentioned vehicles, coolant can get into the gear oil circuit on account of an internal leak in the coolant radiator. This can lead to the automatic transmission oil circuit overflowing and may lead to complaints about the automatic transmission.

A leak cannot be detected on the outside of the radiator.

The problem has already been taken up by the vehicle manufacturer and a remedy found within the context of a service campaign. It must be assumed, however, that not all vehicles were checked or improved for various reasons, or that not all vehicle owners followed the call to bring their vehicles in.

In the meantime, the coolant radiator has been modified by the vehicle manufacturer.

Please bear this information in mind when complaints are made about loss of coolant and the level of gear oil being too high.

Bulletin