## BULLETIN



## Vauxhall Astra J Model year: 2010 - 2011 Engine: A14NEL + A14 NET

## Air-conditioning system not working

The vehicles mentioned above may experience a failure of the air-conditioning system. A defective coolant thermostat must be considered as a possible cause for such failures.

When the motor is switched off and is still warm from operation, the coolant temperature increases (to 130°C). As a result, the thermostat opens "up to the limit stop." It can get stuck in this position. The on-board electronics system interprets this as a faulty temperature setting and switches off the air-conditioning system. The error code P0128 (coolant thermostat) is then stored in the error memory.

In order to remedy this situation, the thermostat should be replaced and the error memory cleared.

Page 1 of 1

© HELLA KGaA Hueck & Co., Lippstadt

2016

The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, pictures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.

