



Opel

Corsa C, from model year 2002

Astra G, Zafira, Meriva from model year 2003

Turbine-like noises

At engine speeds between 2500 and 3000 rpm in the Corsa C, Astra G and Zafira (F75) models and during idling in the Meriva, turbine-like noises can be produced by the air conditioning system. Before replacing any components, the following procedure should be followed for all models:

- Check the refrigerant filling level and correct if necessary
- Check the routing of the refrigerant pipes. These must not touch any bodywork or engine parts.

In addition for Astra and Zafira models with Z16XE and Z18XE engines

- Reduce refrigerant filling level from 600 to 525 g

Bulletin