



## **Opel Frontera B** **Model Year: 1999-2000** **With 2.2 Litre Diesel Engine (X22DTH)**

### **Noises from Air Conditioning**

On the above vehicles, with the chassis numbers listed below, it is possible for noises to occur in the area of the evaporator. These result from the design of the evaporator and expansion valve. In the event of complaints, the evaporator and expansion valve can be replaced with a modified version.

Affected chassis nos.:

XV 600180 up to and including YV 618254 (LHD)  
XV 600180 up to and including YV 624300 (RHD)

**Bulletin**