



Opel

Meriva B

Model year: 2010 - 2012

With air-conditioning system

Loss of oil from the compressor/ Loss of coolant

The above vehicles can experience a compressor leakage. This is mostly noticeable by escaping oil/dye. To fix this problem, the compressor must be exchanged with a modified version:

Old part number:	Corresponding new replacement part number:
13 271 266	13 395 693
13 271 267	13 395 694
13 271 268	13 395 695
13 271 269	13 395 696
13 271 264	13 395 696

Vehicles from the 2012 model year including chassis number B4408747 use factory modified compressors.

Bulletin