



## **Opel Movano Model year: 1998-2001 Engine: 2.5D (S8U)**

### **Coolant loss**

On account of a faulty seal between the cylinder head and the thermostat housing, there can be a loss of coolant in the above-mentioned vehicles.

To eliminate the problem proceed as follows:

- Remove the valve cover and the filter housing
- Separate the hose between the thermostat housing and radiator (collect coolant)
- Separate the coolant hose and the connecting plug on the thermostat housing
- Remove the thermostat housing
- Remove the residual seal and degrease the sealing surfaces
- Attach the thermostat housing to the cylinder head with a new seal (torque 25 Nm), use a suitable sealing agent if appropriate
- Reinstall the other components in reverse order, use a new seal for the valve cover
- Refill the coolant and vent the cooling system
- Bring the engine to operating temperature
- Carry out a leak test

**Bulletin**