Bulletin



© Behr Hella Service GmbH, Schwäbisch Hall	01. Oktober 2005	1-1	
--	------------------	-----	--

Opel Movano Model year: 1998 – 2000 Engine: S8U-2.5 D (770) + S9W-2.8 DTI (702)

Fogged windscreen / Loss of coolant

In the case of the above-mentioned vehicles, fogging of the windscreen may occur in conjunction with loss of coolant. At the same time, coolant can also be found on the floor covering in the vehicle interior. In this case, the heater core is probably defective.

The following points should be observed individually when replacing the heater core:

- Allow the coolant to cool down
- Catch the coolant when draining
- Flush the cooling system with warm tap water
- Fill up the cooling system with coolant and antifreeze (use suitable antifreeze only) in accordance with the stipulated mixing ratio
- Vent the cooling system circuit
- Clean/dry the floor covering
- Carry out a leak test and a functional test

<u>CAUTION</u>: Please note that in the case of many Vehicle models, the radiator fan may start even after switching off the engine or the ignition – Danger of injury.



