



Opel Omega B ***With automatic air conditioning***

Control unit changes mode automatically / No automatic increase of fan stage

If with the above-mentioned vehicles the control unit switches independently to "automatic" mode and the pre-set temperature of 23°C after the ignition has been switched on, this can be due to a faulty control unit. A further indication for the fault could be that the fan stages are not automatically increased when the engine is started up. There is no entry made in the fault store which means that usually the control unit itself is the cause of the problem and has to be replaced.

Bulletin